

Appendix

NOTICE OF VIOLATION

Metal Processing Corporation

License No. 34-16837-01

As a result of the inspection conducted on March 4, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition 14.(A)(1) requires each sealed source containing licensed material, other than Hydrogen 3, with a half-life greater than thirty days and in any form other than gas shall be tested for leakage and/or contamination at intervals not to exceed six months.


Contrary to this requirement, your 100 millicurie and 50 millicurie cesium-137 sealed sources were tested for leakage on January 25, 1983, March 31, 1982 and June 11, 1981. These intervals do not meet the six month requirement.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

3/29/83


D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2