

Alabama Power Company
40 Inverness Center Parkway
Post Office Box 1295
Birmingham, Alabama 35201
Telephone 205 868-5581

W. G. Hairston, III
Senior Vice President
Nuclear Operations

December 20, 1990



Docket No. 50-364


U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555

Joseph M. Farley Nuclear Plant - Unit 2
Special Report No. 90-010, Fire Barrier
Penetration Open For More Than Seven Days

Gentlemen:

In accordance with the requirements of Technical Specification 3.7.12, the enclosed Special Report No. 90-010, Unit 2, is submitted.

Respectfully submitted,


W. G. Hairston, III

WGH,III/DEM:sh 26.08

Enclosure

cc: Mr. S. D. Ebnetter
Mr. S. T. Hoffman
Mr. G. F. Maxwell

JE22
1/1

Special Report No. 90-010, Unit 2
Fire Barrier Penetration Open For More Than Seven Days

The containment equipment hatch was open for more than seven days during the Unit 2 seventh refueling outage. The hatch was opened to support outage activities. The seven-day time limit for the equipment hatch was exceeded on 11-28-90. Since the containment wall is considered to be a fire barrier, opening this hatch constitutes breaching a fire barrier.

Technical Specification 3.7.12 requires that within one hour, either establish a continuous fire watch or verify the operability of fire detectors and establish an hourly fire watch patrol. Technical Specification action statement requirements were met when the hatch was open. Technical Specification 3.7.12 also requires that breached fire barriers be restored to functional status within seven days or a Special Report must be submitted within the following 30 days. Therefore, this Special Report is being submitted.

Due to the scope of the work in progress, it was not practical to close this hatch within seven days. The containment equipment hatch was closed on 12-01-90.

DEMc:sh 26.08