



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II
101 MARIETTA STREET, N.W., SUITE 2900
ATLANTA, GEORGIA 30323-0199

Report No.: 50-395/94-18

Licensee: South Carolina Electric & Gas Company
Columbia, SC 29218

Docket No.: 50-395

License No.: NPF-12

Facility Name: Virgil C. Summer Nuclear Station Unit 1

Inspection Conducted: July 18-21, and August 15-18, 1994

Inspector: David H. Thompson 8-31-94
David H. Thompson, Safeguards Inspector Date Signed

Accompanying Personnel: Lori Stratton, Safeguards Inspector
William J. Tobin, Senior Safeguards
Inspector

Approved by: Douglas M. Collins 8-31-94
for David R. McGuire, Chief Date Signed
Safeguards Section
Nuclear Materials Safety and
Safeguards Branch
Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This routine, announced inspection was conducted in the areas of Safeguards Information, Alarm Stations, Security Training and Qualification, Emergency Event, and the Steam Generator Replacement planned for September 1994.

Results:

In the areas inspected, the following violations were identified:

- A. Safeguards Information was left unsecured and unattended for approximately 15 hours and the licensee failed to notify the NRC within the required one hour timeframe. (Paragraph 2)
- B. The compromise of Safeguards Information was not logged in the Safeguards Event Log as required by procedure. (Paragraph 2)

9409130457 940901
PDR ADOCK 05000395
G PDR

SAFEGUARDS INFORMATION

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosures, this document is decontrolled.

SAFEGUARDS INFORMATION

2

- C. Alarm station operators failed to acknowledge and respond to a vital area door alarm for assessment in the required time limit. Supervisors failed to adequately review the alarm station records to ensure that the alarm station operators had properly followed procedures. (Paragraph 3)

The inspectors determined that in the Security Training and Qualification area that the licensee exceeded the commitments of 10 CFR 73, Appendix B. The inspectors reviewed an event which occurred on August 16, 1994, relating to a tornado emergency which caused the licensee to suspend safeguards criteria for access control. The licensee effectively implemented applicable provisions of the Physical Security Plan and procedures relative to this emergency weather event.

SAFEGUARDS INFORMATION

Document transmitted herewith contains sensitive unclassified information. When generated from enclosures, this document is decontrolled