

USNRC REGION II
ATLANTA, GEORGIA

83 MAR 15 AIO: 1



March 10, 1983
L-83-132

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RE: RII: WPA
St. Lucie Unit No. 2
Docket No. 50-389/82-71

Florida Power & Light, on February 11, 1983 provided a Final Response to the violation "Pipe Support Discrepancies". Per telecon with your Mr. J. Blaue on February 22, 1983, Florida Power & Light is providing a supplemental response to the above violation.

On February 17, 1983, subsequent to filing a response to the violation 50-389/82-71-01, FPL was requested per telecon to either reinspect the original sample of 125 hangers for all characteristics or select 50 more hangers from the group in question and inspect them for all characteristics. FPL elected the later and reported the results to Mr. J. Blake of Region II on February 22, 1983. Discrepancies were found, though of a minor nature; therefore, FPL committed to reinspecting the approximately 525 hangers remaining from the original 1981 group. Restraints not accessible will be reviewed for reinspections which have been performed during 1982 and 1983.

All discrepancies noted will be documented per applicable site procedures. All reinspections will be completed by March 11, 1983.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems and Technology

8304110401 830318
PDR ADOCK 05000389
Q PDR