

APR 12 1991

In Reply Refer To:
License: 49-23172-01
Docket: 030-20338/91-01

PMPC Consulting Engineers
ATTN: Paul McCarthy
P.O. Box 370
Saratoga, Wyoming 82331

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Messrs. Selvan Rajendran and Gilbert L. Guerra, Jr., of this office on February 6, 1991, of activities authorized by NRC Byproduct Material License No. 49-23172-01, and to the discussion of our findings held by the inspectors with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspectors.

No violations or deviations were identified.

The inspectors also reviewed actions you had taken with respect to the violation observed during our previous inspection conducted on June 11, 1986. They verified that corrective actions for the violation had been implemented per NRC Form 591 dated June 11, 1986.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed By

A. B. BEACH

A. Bill Beach, Director
Division of Radiation Safety
and Safeguards

cc:
Wyoming Radiation Control Program Director

RIV: NMLS RA
SRajendran: law
3/29/91

NMLS C⁶
GGuerra
3/29/91

C: NMLSh
WLFisher
4/10/91

AD: DRSS
ABBeach
4/12/91

9104220023 910412
REG4 LIC30
49-23172-01 PDR

IE-07
110

PMPC Consulting Engineers

-2-

bcc:

DMB - Original (IE-07)

RDMartin

ABBeach

LAYandell

MRodriguez, OC/LFDCB (4503)

*WLFisher

*CLCain

*SRajendran

*GGuerra

*NMLS

*MIS System

*RIV Files (2)

*RSTS Operator

*REHall, URFO

*W/766