LICENSEE EVENT REPORT

	사용하는 경우는 경우는 그 사람들은 경우를 가득하는 것이 없다면 그렇게 되었다면 그렇게 되었다면 하는데 하는데 그렇게 되었다면 하는데
	CONTROL SLOCK 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
01	MI I D C C 2 0 0 - 0 0 0 0 0 - 0 0 0 0 0 0 0 0 0 0
CON'T	SCHAGE LIGID! 5 1 0 0 0 3 1 6 0 0 3 0 2 8 3 8 0 1 3 3 1 8 3 9
07	A SECURITY OFFICER WAS DISPATCHED TO CHECK CD DIESEL ROOM DOOR FOR SECURITY. THE
0 3	OFFICER DISCOVERED THE CO2 SYSTEM ISOLATED WITH NO PERSONNEL IN ROOM. THIS WAS
0 4	LMON-CONSERVATIVE WITH RESPECT TO T.S. 3.7.9.3. FIRE DETECTION SYSTEM (THERMISTORS)
(a)(3)	LREMAINED OPERABLE. THE HEALTH AND SAFETY OF THE PUBLIC WERE NOT AFFECTED.
[16]	LPREVIOUS OCCURRANCES WERE REPORTED VIA 316/82-076, 315/82-037, 315/82-044,
[3]]	(315/82-045, 315/82-068, AND 316/82-054.
018	80
09	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
7 8	SEQUENTIAL OCCURRENCE REPORT REVISION REPORT NO. CODE TYPE NO.
	(17) REPORT 8 3 - 10 2 8 2 10 3 1
	ACTION FITURE STREET SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. N (24) N (25) C 1 2 5 (26)
	CAUSE DESCRIPTION AND CORRICTIVE OCTIONS (27)
10	THE RESPONSIBLE EQUI MENT OPERATOR WAS CONTACTED AND THE SYSTEM WAS RETURNED TO
	L NORMAL . THE TWO OPERATORS HAVE BEEN REINSTRUCTED AS TO THE PROPER METHOD OF
12	LENTERING A CO2 PROTECTED AREA. NO FURTHER ACTION PLANNED.
III	
Ta	
15	ACILITY DISCOVERY DESCRIPTION (32) E (3)
	LOCATION OF RELEASE 36 NA NA
8	PERSONNEL EXPOSURES DESCRIPTION (39)
1 7	LOLOLOLOLOLOLOLOLOLOLOLOLOLOLOLOLOLOLO
1	NUMBER DESCRIPTION (1) NA
8	urs of OR UNIACT TO FACILITY (3) NA
11	
201	PUBLICITY SSUED DESCRIPTION 45 NA
9	68 69 80 5
836	NAME OF PREPARER D. F. VIAUSE PHONE: (616) 465-5901 &