## MATERIAL TRANSMITTED MEREWITH CONTAINS

## 2.790 INFORMATION U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

Region V

Report No. 110-02915/83-01 (IE-V-559)

Docket No. 110-02915

License No. XSNM-1976 Safeguards Group IX

Licensee: Marubení America Corporation

650 California Street

San Francisco, California 94108

Inspection at: C.F.S. 5110 7th Street, Oakland

Inspection Conducted: April 6, 1983

Type of Inspection: Material Control and Accounting, Safeguards

Inspectors:

G. B. Nelson, Chemist

4-12-83 Date Signed

Cospone

. Pang, Radiation Specialist

D.A Skov, Radiation Specialist

eder Safeguards Auditor

4-12-83

Date Signed

Approved by:

R. Norderhaug,

Safeguards Branch

Inspection Summary:

Areas Inspected: Verified shipping drum identification and tamper seal numbers to the shipment packing lists; confirmed gross drum count; shipping container and tamper seal integrity; compared quantitative date with amounts authorized by NRC export license as shown in the shipping papers; monitored external radiation level and wipe checked each drum surface for detectable contamination. This inspection involved 9 hours of on-site time by four NRC inspectors.

Results: No items of noncompliance were noted.

MATERIAL TRANSMITTED HEREWITH CONTAINS 2.790 INFORMATION