



# Mercy Hospital

2200 Jefferson Avenue

Toledo, Ohio 43624

(419) 259-1500

April 4, 1983

Mr. J.R. Miller, Chief  
Materials and Safeguards Branch  
The United States Nuclear Regulatory  
Commission, Region 3  
799 Roosevelt Road  
Glenn Ellyn, Illinois 60137

License No. 34-00305-03

Dear Mr. Miller:


This letter is a follow-up to a telephone call received from Rose Douglas regarding our letter to you dated March 16, 1983. The following is additional information requested:

License No. 34-00305-03

- 6-b. Additional information - A 24-hour uptake will be performed on the administering physician and the results recorded on Exhibit 6 page 1, entitled "I-131 Therapeutic Dose - Personnel Survey".
- 7-b. Additional information - If constancy check varies by more or less than 5%, the dose calibrator will be recalibrated.
- 9. Additional information - Leak testing will be performed every six (6) months.

We trust this will complete the information you requested on violations noted in your Appendix A.

Sincerely,

  
Leonard P. Hofer  
Assistant Administrator

APR 7 1983

8304180288 830413  
NMS LIC30  
34-00305-03 PDR

A Sisters of Mercy Health Care Facility