

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T

0	1	L	6	0	5	0	0	0	3	1	7	7	0	3	0	7	8	3	8	0	4	0	6	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	At 1500 during normal operation, hydrogen analyzer O-AE-6519 was found																																																																														
0	3	to be out of service. The purge gas bottle was replaced and the analyzer																																																																														
0	4	returned to service at 1620. The redundant hydrogen analyzer remained																																																																														
0	5	operable during this event. Unit 2 was in Mode 3.																																																																														
0	6	Similar events: none.																																																																														
0	7																																																																															
0	8																																																																															

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0	9	I	E	11	D	12	X	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	3	18	0	1	3	19	0	3	20	L	21	0	22	C	18	G	19	Z	20	Z	21	0	0	0	0	22	N	23	N	24	Z	25	Z	9	9	9	9	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	---	---	----	---	---	---	----	---	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	---	---	---	----	---	----	---	----	---	----	---	---	---	---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The cause of the event was the inadvertent depletion of a purge gas																																																																														
1	1	(oxygen) cylinder. The operations logs change report has been initiated																																																																														
1	2	to monitor the cylinder tank pressure. This log revision should																																																																														
1	3	eliminate the recurrence of this event.																																																																														
1	4																																																																															

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	5	E	28	1	0	0	29	N/A	30	A	31	Operator Observation																		32
1	6	Z	33	Z	34	N/A	35	N/A	36	N/A																				37
1	7	0	0	0	37	Z	38	N/A	39																					40
1	8	0	0	0	40	N/A	41																					42		
1	9	Z	42	N/A	43																					44				
2	0	N	44	N/A	45																					46				

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 808304120314 830406
PDR ADDCK 05000317
S PDR

NRC USE ONLY

NAME OF PREPARER J. S. Lagiewski/J. M. Bills

PHONE 301-269-4747/4795