

DCV/DCB

Cameron



Maynard Steel Casting Company

DIAL: 645-0440 AREA 414
2856 SOUTH 27th STREET
MILWAUKEE, WIS., 53215

April 1, 1991

U.S. Nuclear Regulatory Committee
Region 3
799 Roosevelt Road
Glen Ellen, IL 60137

48-07080-01

ATTENTION: Mr. William H. Schultz

Dear Mr. Schultz:

This is in regards to the letter we received on March 15, 1991, concerning the inspection that was done here. Docket No. 030-06743.

- 1) Concerning our Radiographer and the "Alara" Philosophy, he has been reprimanded and told that he will be written up and given a three day lay-off if he doesn't listen to and follow the guidelines which have been laid out for all radiographers.
- 2) In regards to not performing a leak test on a sealed source, as I told Mr. Cameron, we performed the leak test and sent it in with the other leak test. We did not get the results back for almost eight weeks. Upon receiving the results, we received only one test result, not two. I called the testing lab and they could not find the other envelope in which it was sent. As Mr. Cameron explained to me, I should have taken another leak test at that time.
- 3) In regards to having the improper shipping name, I have called Amersham Corp. and asked what we should have put down. They told me "Radioactive Material, Special forms, No's UN2974". To correct the situation so it doesn't happen again, when we receive a new source, we will call and verify what we should put on the packing slip for the source we are sending back.



9105070004 010401
REC3 LIC30
48-07080-01 PDR

JE07

110

060022

48-07080-01

- 4) In regards to the transport index and wrong labels on the package, I checked into it further and found the correct labels were on the package, "Radioactive Yellow II, DOT-Transportation Index 1". The receiving report from Amersham shows they received the package with a DOT-T.I. of "1" on it. Our shipping clerk made a typing error on the packing slip and 4.5.

I will monitor the above infractions as so they do not happen again.

Sincerely,

MAYNARD STEEL CASTING COMPANY



Paul Frank
Chief Radiographer

PF/bmh