



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 29, 1983

L. V. MAURIN
Vice President Nuclear Operations

W3183-0142
Q-3-A35.07.53

Mr. John T. Collins
Regional Administrator, Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit Number 3
Docket Number 50-382
Significant Construction Deficiency Report Number 52
"Possible Failure of General Electric Type HFA Relays"
Third Interim Report

REFERENCE: LP&L Letter WI82-0051 dated September 30, 1982

IE-27

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than April 30, 1983.

At the present time, corrective action is scheduled for completion on May 20, 1983. This is due to the fact that corrective action cannot be performed during plant testing. A final report will therefore be delayed until June 15, 1983.

Very truly yours,

L. V. Maurin
L. V. Maurin

LVM/MAL/sm

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8305060587 830429
PDR ADOCK 05000382
S PDR