

142 DELARONDE STREET . PO BOX 6008

· (504) 366-2345

AUG 1 5 1983

August 5, 1983

W3183-0272 Q-3-A35.07.55

Mr. John T. Collins, Regional Administrator, Region IV U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 55 "Hold Up and Boric Acid Make Up Tanks Incorrect Structural Calculations"

REFERENCE: LP&L letter W3183-0220 dated June 23, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than August 5, 1983.

At the present time, the supporting documentation is under review and a Final Report is in preparation.

A Final Report will therefore be submitted to the USNRC by September 7, 1983.

Very truly yours,

F. J. Drummond

Manager Engineering & Technical Services

FJD/WAC/MAL; keh

cc: 1) Director Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

3) Mr. E. L. Blake

2) Director Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555

4) Mr. W. M. Stevenson

8308220252 830805 PDR ADOCK 05000382