

APPENDIX A

NOTICE OF VIOLATION

Firestone Tire and Rubber Company

License No. 45-06454-01

As a result of the inspection conducted on May 16, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified.

- A. License Conditions 10 and 11 requires that two Nuclear Chicago Model 2650. radiation detection instruments be possessed by the licensee, and that these instruments will be kept in calibration using a Nuclear Chicago Model 18160 calibration source.

Contrary to the above, on May 16, 1983, only one instrument was possessed by licensee and no record of calibration could be located.

This is a Severity Level V Violation (Supplement VI).

- B. 10 CFR 19.11(a) and (b) require that current copies of Part 19, Part 20, the license, license conditions, documents incorporated into the license, license amendments and operating procedures be posted, or that a notice be posted describing these documents and where they may be examined.

Contrary to the above, on May 16, 1983, neither the documents nor the notice were posted.

This is a Severity Level IV Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

JUN 15 1983

Date: _____

8308230265 830816
NMS LIC30
45-06454-01 PDR