

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY
STATION MANAGER

August 8, 1983

RECEIVED
NRC

1983 AUG 12 AM 11:03

SCE

REGION V

TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J.B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
Special Reports (Docket No. 50-361)
Licensee Event Report Nos. 83-036, Rev. 1 and 83-042
(Docket No. 50-362)
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, H.B. Ray (SCE) to J.B. Martin (NRC),
dated May 3, 1983

The referenced letter provided you with the required 30-day Special Report pursuant to Section 3.3.3.7, Action Statement 'b' of Appendix A, Technical Specifications to Operating License NPF-10 for San Onofre Unit 2, and the Licensee Event Report (LER) No. 83-036 pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Operating License NPF-15 for San Onofre Unit 3 for occurrences involving inoperable fire detection instrumentation.

The fire detector failures in Zone 6 and Zone 41 were reported as a single event since the method of discovery and manufacturer of the components were the same for both events. As specified in the referenced report, the cause of the fire detector failures was not known and we have continued to investigate this event. The Zone 6 and 41 detectors have since been repaired and the cause of the failures was found to be different, therefore necessitating the submittal of separate reports for the two events.

The Unit 2 license requires these type events to be reported as a Special Report whereas the Unit 3 license requires an LER. Accordingly, this submittal provides you with a copy of Revision 1 to LER No. 83-036 for Unit 3 addressing the Zone 41 fire

8308240003 830808
PDR ADOCK 05000362
PDR
S

11


IE-22
83-321

August 8, 1983

detectors, and also provides you with a copy of LER No. 83-042 for Unit 3 addressing the Zone 6 fire detector, and constitutes the Special Reports required by Technical Specification 3.3.3.7, for San Onofre Unit 2.

If there are any questions regarding the above, please contact me.

Sincerely,



Enclosures: LER No. 83-036, Revision 1 (Unit 3)
LER No. 83-042 (Unit 3)

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
J.P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)