



Log # TXX-94200
File # 10200
Ref. # 10CFR50.73(a)(2)(v)

October 5, 1994

C. Lance Terry
Group Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES) - UNIT 2
DOCKET NO. 50-446
LICENSEE EVENT REPORT 446/94-005-00

REF: TU Electric letter logged TXX-94166 from William J. Cahill, Jr.
to the NRC dated June 17, 1994

Gentlemen:

Via the referenced letter TU Electric submitted Licensee Event Report (LER) 94-005-00 for Comanche Peak Steam Electric Station Unit 2, "Continued Vibration Induced Fatigue Led to Failures of Additional Welds in the Containment Spray System." This transmittal noted a supplemental report would be forthcoming.

During the August 9, 1994, Enforcement Conference related to the apparent violations identified in NRC Inspection Report 50-445/94-14, TU Electric stated that as an enhancement new pump impellers will be installed during the upcoming Unit 2 refueling outage. After the impeller installations have been completed and tested, an evaluation will be made to determine whether the standard 4 vane or the offset 5 vane impeller is preferable.

On September 27, 1994, TU Electric informed Mr. D. D. Chamberlain of your staff, that it would be more appropriate to issue a supplement to the subject LER after the proposed actions are complete. The supplemented LER will be issued after these actions have been finalized subsequent to the completion of 2RF01.

10200

9410140061 941005
PDR ADDOCK 05000446
S PDR

400 N. Olive L.B. 81 Dallas, Texas 75201

JE27 10

TX-94200
Page 2 of 2

Should you have any questions please contact Obaid Bhatti at
(817) 897-5839.

Sincerely,

C. L. Terry

C. L. Terry

By: *Roger D. Walker*
Roger D. Walker
Regulatory Affairs Manager

OB:tg

cc: Mr. L. J. Callan, Region IV
Mr. D. D. Chamberlain, Region IV
Resident Inspectors, CPSES