


DMB




MSI TESTING, INC.

80 EAST 2770 SOUTH - SALT LAKE CITY, UTAH 84115

TEL. (801) 484-8803 - TWX 910-925-5613

7/28/83

Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



ATTN: Glen D. Brown

SUBJECT: Response to Notice of Violation
Docket: 30-12265
License: 43-17142-01

Gentlemen:


In response to your letter dated 15 July 1983, we would like to submit the following corrective action and dates of compliance.

- (A) Violation - 49CFR72403 (a), labeling per 49CFR172403 (b) - (g) corrective action:
 1. All temporary storage and transporting containers shall be labeled with two labels, with one label on each of two opposite sides of the container. Each label shall be "Radioactive Yellow II", each shall also be labeled with the isotope, number of curies and transport index.
NOTE: A Yellow II sticker will be used because the shielding required by our operating procedure requires the levels to be in a Yellow II classification.
 2. Each container shall also be marked with the words "Inside Package Complies with Prescribed Specification".
Compliance date: 8/8/83

- (B) Violation 49CFR173.25 (b)
Corrective action: See (A) 2 above.
Compliance date: 8/8/83.

Should you have any further questions please contact us.

Sincerely,



Brent Mockli
NDE Supervisor

8309070327 830728
NMS LIC30
43-17142-01 PDR

(J207) 110