

REVISED
6/15/83

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH February, 1982

DOCKET NO. 50-369
UNIT NAME McGuire 1
DATE 3/15/82
COMPLETED BY J.A. Reavis
TELEPHONE (704) 373-8552

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
2-p	82-02-01	F	--	H	--		CB	HTEXCH	Holding at 50% power until an outage for further inspection and analysis of steam generator condition.
7	82-02-05	F	12.25	B	3		ZZ	ZZZZZZ	Reactor tripped due to a procedure deficiency while performing a periodic test.
3-p	82-02-06	F	--	H	--		CB	HTEXCH	Holding at 50% power until an outage for further inspection and analysis of steam generator condition.
8	82-02-16	F	13.20	A	3		HH	PUMPXX	Trip of condensate booster pumps resulted in a reactor trip.
4-p	82-02-17	F	--	H	--		CB	HTEXCH	Holding at 50% power until an outage for further inspection and analysis of steam generator condition.

- 1
1 - Forced
S - Scheduled

- 2
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

- 3
Method:
1-Manual
2-Manual Scram
3-Automatic Scram
4-Other (Explain)

- 4
Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

- 5
Exhibit I - Same Source

REVISED
6/15/83

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH February, 1982

DOCKET NO. 50-369
UNIT NAME McGuire 1
DATE 3/15/82
COMPLETED BY J.A. Reavis
TELEPHONE (704) 373-8552

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
9	82-02-26	F	5.98	A	3		ZZ	ZZZZZZ	The loss of a 125V AC power supply resulted in a unit trip.
9A	82-02-26	F	53.00	B	--		CB	HTEXCH	Began a 16-day outage for steam generator tube EC-and analysis.

¹
F - Forced
S - Scheduled

²
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

³
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Other (Explain)

⁴
Exhibit G - Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER) File (NUREG-
0161)

⁵
Exhibit I - Same Source

REVISED
6/15/83

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH July, 1982

DOCKET NO. 50-369
UNIT NAME McGuire 1
DATE _____
COMPLETED BY _____
TELEPHONE _____

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
12	82-07-01	F	216.00	B	--		CB	HTEXCH	Outage continues for inspection of steam generator tubes. Thermal sleeve problem.
12A	82-07-10	F	179.03	B	--		CB	HTEXCH	
9-p	82-07-17	F	--	H	--		CB	HTEXCH	Holding at 50% power awaiting further analysis of steam generator condition.
13	82-07-21	F	7.17	G	3		HA	TURBIN	Turbine/reactor trip during periodic turbine trip test due to operator error.
10-p	82-07-21	F	--	H	--		CB	HTEXCH	Holding at 50% power awaiting further analysis of steam generator condition.

¹
F: Forced
S: Scheduled

²
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

³
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Other (Explain)

⁴
Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NURLG-0161)

⁵
Exhibit I - Same Source