

IE-07
PUBLIC 11/0

OCT 24 1994

Midwest Environmental Consultant, Inc.
ATTN: C. Michael Smith
President
5902 Southwyick Blvd.
Toledo, OH 43614

Dear Mr. Smith:

This refers to the routine safety inspection conducted by Mr. J. L. Cameron of this office on September 16, 1994, of activities authorized by NRC Byproduct Material License No. 34-26110-01, and to the discussion of our findings with Mr. M. Momenee at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,
Original Signed by B. J. Holt

B. J. Holt, Chief
Nuclear Materials Inspection
Section 1

License No. 34-26110-01
Docket No. 030-31467

bcc: PUBLIC 040031

DOCUMENT NAME: G:\insprpts\mtls\030\03031467.941

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	DRSS/NMLS/RIII <input checked="" type="checkbox"/>	DRSS/NMLS/RIII						
NAME	JCameron:bt <i>JIC</i>	BJHolt <i>BJH</i>						
DATE	10/21/94	10/24/94						

9411070010 941024
PDR ADOCK 03031467
C PDR