NRC FOR (12-81) 10 CFR 50	M 366	LICENSEE EVENT REPORT	APPROVED BY- 3MB 3150-0011
	CONTROL BLOCK:	(PLEASE PRINT OR TYPE	ALL REQUIRED INFORMATION
01	C A D C P 1	0 0 0 - 0 0 0 0 0 0 - 0 0 0 4	1 1 1 1 1 0 57 CAT 35
CONT	SOUNCE LOO 5	0 0 0 0 2 7 5 0 0 6 0 6 8 3	10 017 0 5 8 3 0
-	Prior to fuel load.	the Plant Vent Flow Rate Monitor (FF	R-12) was discovered to
0 3	be deenergized. FF	-12 was declared Inoperable. Technic	cal Specification 3.3.3.10
0 4		ere satisfied and no radioactive eff	
0 5	This event has in n	o way affected the public health and	safety. Reportable per
0 6	Technical Specifica	tion Section 6.9.1.13.b.	
0 7			The state of the s
08			
0 9		LA 12 LA 3 LINIS TIRU	E 19 Z 10
	TO REPORT 8 3		
Î	X 18 H 19 Z 20	HOURS 22 ATTACHMENT NAME OF THE PORMS NAME OF TH	UB SUPPLIES MANUFACTURES
	Personnel error. D	nective actions (27) uring intense construction activity,	operations
111	personnel deenergiz	ed several instrument power circuits	to allow construction
1 2	work in cabinets wi	thout performing a thorough research	of equipment power
13	supplies. Operation	ns personnel were cautioned to thorou	ighly research all
7 . 1	clearance requests	O MUTHOR OF	80
	B @ 0 0 0 0 0 N	OTHER STATUS (30) DISCOVERY DISCO	oservation 32
16	TIVITY CONTENT AMOUN Z 33 Z 34 NA	TOF ACTIVITY (35) NA	TION OF RELEASE (36)
17	O O O O Z 38 N	A A	102
	PERSONNEL INJURIES NUMBER DESCRIPTION		TEN.
18	O O O O O O DAMAGE TO PACILITY		
	Z 42 NA		•
20	N 40 NA	8307220271 830705 PDR ADDCK 05000275 S PDR	NRC USE ONLY
	NAME OF PREPARER	William J. Kelley PHO	(805) 595-7351

PACIFIC GAS AND ELECTRIC COMPANY

IP G WIE

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106• (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER
MANAGER
DEPARTMENT OF NUCLEAR PLANT OPERATIONS
NUCLEAR POWER GENERATION

July 5, 1983

Mr. John B. Martin, Regional Administrator U.S Nuclear Regulatory Commission, Region V 1450 Maria Lane, Suite 210 Walnut Creek, CA 94596-5368

Re: Docket No. 50-275, OL-DPR-76

Diablo Canyon Unit 1

Licensee Event Report 83-016/03L-0 Inoperable Plant Vent Flow Monitor

Dear Mr. Martin:

Pursuant to Section 6.9.1.13.b of the Technical Specifications, Appendix A to the Dirolo Canyon Unit 1 Operating License, the enclosed Licensee Event Report is submitted concerning an inoperable Plant Vent Flow Rate Monitor.

This event has in no way affected the public's health and safety.

Very truly yours,

Enclosure

cc w/enc:

Mr. George Knighton, Chief Licensing Branch No. 3 Division of Licensing Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Director, Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Service List

BEGION A 18/5

1983 JUL -7 AM 11: 22

HECEINED

11 IE-22 83-151