



**LOUISIANA**  
POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 8008  
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 366-2345

July 21, 1983

W3P83-1225  
Q-3-A29.20

Director of Nuclear Reactor Regulation  
Attention: Mr. G. W. Knighton, Chief  
Licensing Branch Number 3  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

SUBJECT: Waterford 3 SES  
Docket No. 50-382  
SER Issues - ECCS Preop Test

Dear Sir:

As part of our effort in closing-out SER issues, we have identified the following License Condition which we believe should be deleted:

Preoperational Test of ECCS (License Condition) - ECCS preop testing is ongoing and will be completed as required by FSAR Sections 6.3 and 14.2. If test results from any preop test differ from the specified acceptance criteria, the results are evaluated and reported as required by 10CRF50.55(e).

It is our understanding that it is inappropriate to specify as a License Condition one aspect of the startup test program when controls are in place to ensure that the specified acceptance criteria are met. As such, we request that an SER Supplement be written to remove this License Condition.

If you have any questions regarding this matter, please feel free to contact Roy Prados at (504) 363-8773.

Yours very truly,

F. J. Drummond  
Project Support Manager-Nuclear

FJD/RMF/ssd

cc: E. L. Blake, W. M. Stevenson, J. Wilson (NRC), L. Constable

8307260568 830721  
PDR ADDCK 05000382  
E PDR

Boo!  
1/0