




**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 25, 1983

W3183-0246
Q-3-A35.07.66

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 66
"Defective G.E. Type AKR Breakers, C-Clips Fall Off"
Fourth Interim Report

REFERENCE: LP&L letter W3183-0222 dated June 29, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than August 5, 1983.

At the present time, the completion of corrective action is being delayed due to testing. We are presently awaiting an opportunity to install the c-clips without impacting the startup schedule. This installation is expected to be complete by late August, 1983.

A Final Report will therefore be submitted to USNRC by September 16, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 3) Mr. E. L. Blake
- 4) Mr. W. M. Stevenson

8308030001 830725
PDR ADOCK 05000382
S PDR

IE-27 110