JUL 2 9 1983

Docket No. 70-270 Docket No. 50-186

University of Missouri ATTN: Dr. Don M. Alger Acting Director Research Reactor Facility Research Park Columbia, MO 65201

Gentlemen:

This refers to the routine safeguards inspection conducted by Mr. T. J. Madeda and Ms. G. M. Christoffer of this office on July 13-15, 1983, of activities at the University of Missouri - Columbia authorized by NRC Operating License No. R-103 and NRC Special Nuclear Material License No. SNM-247 and to the discussion of our findings with you and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

Areas examined during the inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, our report of this inspection will not be placed in the Public Document Room.

8308030056 830729 PDR ADOCK 05000186 Q PDR

ATTACHMENT CONTAINS 10 CFR 2.790(d) INFORMATION DMB: IFO2 University of Missouri

We will gladly discuss any questions you have concerning this inspection.

2

Sincerely,

Original Signed by J. R. Miller

J. R. Miller, Chief Materials and Safeguards Branch

Enclosure: Inspection Reports No. 50-186/83-02(DRMSP) and No. 50-270/83-01(DRMSP) (PART 2.790(d) INFORMATION)

cc w/encl, w/o PART 2.790(d) INFORMATION: DMB/Document Control Desk (RIDS)

RIII Madeda/sv 07/28/83 RIII Christoffer

RIII Off B Creed RIII Bidgway

ATTACHMENT CONTAINS 10 CFR 2.790(d) INFORMATION