

Appendix

NOTICE OF VIOLATION

Nite-Site, Incorporated

License No. 22-13585-02G

As a result of the inspection conducted on July 28, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 3.D. states, each label required by this condition shall be permanently attached to each gun by Nite-Site, Inc.

Contrary to this requirement, since the previous inspection, the licensee has not always attached the required label to each gun.

This is a repeat item of noncompliance.

This is a Severity Level V violation (Supplement VI).

2. License Condition No. 3.A.(i) states, each gun sight must be tested for leakage at least every three years.

Contrary to this requirement, on the day of this inspection, the inspector was informed that the three year leak testing samples were not always received from the general licensees. The licensee receives no more than 50 percent returns of the leak test samples.

This is a Severity Level V violation (Supplement VI).

3. License Condition No. 5 states, the licensee shall furnish to each general licensee a copy of Appendix D of 10 CFR 20.

Contrary to this requirement, although Appendix D of 10 CFR 20 is referenced in the information distributed to each general licensee, a copy of Appendix D of 10 CFR 20 has not been furnished to each general licensee.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

8-24-82

Dated



D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1