




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

July 28, 1983
RBG- 15,548
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011





Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-121

On June 28, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning discrepancies between equipment internal wiring and vendor wiring diagrams supplied by Gauld-Brown Boveri (DR-121). GSU has not completed its investigation. An interim or final status report will be provided by September 15, 1983.

Sincerely,


for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

 PJD
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)