

DCD/DCB

AUG 08 1991

Michigan State University
ATTN: John Parmer, Acting Director
Office of Radiation, Chemical
and Biological Safety
C124 Research Complex-Engineering
East Lansing, MI 48814

License No. 21-00021-29
License No. 21-00021-30
Docket No. 030-00806
Docket No. 030-06956

Dear Mr. Parmer:

This refers to the inspection conducted by Gary Shear and Michael Kurth of this office from July 9 to July 12, 1991, of activities authorized by NRC Byproduct Material Licenses No. 21-00021-29 and No. 21-00021-30 and to the discussion of our findings with you, Dr. Bieber, and other members of your staff.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities under License No. 21-00021-29 appeared to be in violation of NRC requirements, as specified in the enclosed Notice and a written response is required. No violations were identified for License No. 21-00021-30.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

William Snell, Chief
Nuclear Materials Safety
Section 2

Enclosure: Notice of Violation

cc w/enclosure: DCD/DCB (RIDS)

R111

Kurth/da

yes 8-8-91

yes

R111

was
for Shear

R111

WGS
Snell

8/8/91

9108130157 910808
REG3 LIC30
21-00021-29 PDR

111
IE07