

September 9, 1983

Director of Regulatory Operations U. S. NUCLEAR REGULATORY COMMISSION Washington, D. C. 20555

Gentlemen:

MONTHLY OPERATING REPORTS POINT BEACK NUCLEAR PLANT

Licensed Operating Reactors Status Summary Report, NUREG-0020, Volume 7, Number 3, March 1983, reported an error found in the Exxon LOCA-ECCS analysis resulting in an increase in the peak clad temperature of 13°F for Point Beach Unit 2. This letter is to inform you that this is incorrect as Point Beach has no Exxon fuel.

Very truly yours,

Vice President-Nuclear Power

C. W. Fay

Copy to NRC Resident Inspector

IE24