




**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 2008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 2, 1983

W3I83-0296

Q-3-A35.07.32



Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 32  
"Stress Analysis for Welded Pipe Support Attachments Was Not  
Performed Prior to Fabrication"  
Fifth Interim Report

REFERENCE: LP&L Letter No. W3I83-0219, dated June 23, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than August 31, 1983.

At the present time, the supporting documentation is under review and is expected to be completed by October 14, 1983.

A Final Report will be submitted by October 28, 1983.

Very truly yours,

F. J. Drummond  
Manager, Engineering & Technical Services

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

3) Mr. E. L. Blake

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

4) Mr. W. M. Stevenson

8309230110 830902  
PDR ADDCK 05000382  
S PDR

IE-27 110