

Dmb



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

September 14, 1983


Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-74  
Docket No. 50-316

Dear Mr. Keppler:

On September 1, 1983, notification was made to Mr. E.R. Swanson at 1715 hours that we were removing Unit 2 from service to perform an inspection of the tie-down features of the Pressurizer Enclosure Ventilation System to confirm the statement made in our August 31, 1983, letter (Docket No. 50-315). This inspection confirmed that adequate tie-downs were installed and the Unit was immediately returned to service.

Sincerely,

  
W.G. Smith, Jr.

/bab

cc: John E. Dolan  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E. Swanson/N. DuBry, RO:III  
R.C. Callen, MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)

SEP 19 1983

8309230349 830914  
PDR ADOCK 05000316  
Q PDR

IE22  
110