

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	6	5	7	0	8	1	6	8	3	8	0	9	0	8	8	3	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE							REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1515 hours, on August 16, 1983, following recalibration of the Suppression Pool
0 3 | water temperature indication, QIS 52-1, the temperature was found to be 96 degrees
0 4 | F. This is contrary to the maximum temperature limitation specified in Technical
0 5 | Specification 3.7.A.1.c.1. A Reactor shutdown was immediately initiated. Adequate
0 6 | cooling was still available to provide complete condensation of steam which would
0 7 | be produced during a design basis accident; therefore, the safety consequences of
0 8 | this event are minimal.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE		
S	A	X		X		I	N	S	T	R	U	E	Z	
EVENT YEAR				SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE				REVISION NO.		
8	3	—		0	1	2	/	0	3	L	—		0	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUPPLIER		
E	Z	B		Z					0	0	0	1	N	X
L		0	0	7										

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event was instrument calibration drift. The temperature indicator

1 1 was indicating a lower temperature than the actual water temperature. Suppression

1 2 Pool cooling was initiated immediately; and the temperature was within Technical

1 3 Specification limits by 1550 hours.

1 4

8 9
FACILITY STATUS (28) % POWER (29) OTHER STATUS (30)
1 5 E 0 5 8 NA
7 8 9 10 11 12 13 44

METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)
B Routine Quarterly Calibration
45 46 80

ACTIVITY CONTENT (35)
RELEASED OF RELEASE AMOUNT OF ACTIVITY
1 6 Z Z NA
7 8 9 10 11 12 13 44

LOCATION OF RELEASE (36)
NA
45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

93092304 120800

1 9 Z 42 NA

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY														
2	0	N	44	NA																
7	8	9	10																	

PHONE 309-654-2241, ext 181



Commonwealth Edison

Quad Cities Nuclear Power Station
22710 206 Avenue North
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-83-315

September 8, 1983

J. Keppler, Regional Administrator
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137


Reference: Quad-Cities Nuclear Power Station
Docket Number 50-265, DPR-30, Unit Two
Appendix A, Section 3.7.A.1.c

Enclosed please find Reportable Occurrence Report Number RO 83-12/03L-0
for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of
Technical Specification 6.6.B.2.b; operation in a degraded mode permitted
by a limiting condition of operation.

Respectfully,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION


N. J. Kalivianakis
Station Superintendent

NJK:DGC/bb

Enclosure

cc B. Rybak
A. Morrongiello
INPO Records Center

SEP 14 1983

11

IE22