LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 36 LICENSE TYPE 30 57 CAT 58
ON'T SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
DURING NORMAL PLANT OPERATION, A SECURITY OFFICER FOUND THE CO SWITCH FOR THE
UNIT # 2 CD DIESEL GENERATOR ROOM IN THE ISOLATE POSITION WITH NO ONE IN THE RM.
THIS CONDITION EXISTED FOR 2 HOURS. THIS IS CONTRARY TO THE REQUIREMENTS OF
T.S. 3.7.9.3. THE FIRE DETECTION SYSTEM WAS OPERABLE DURING THIS PERIOD. PUBLIC
[0 16] LHEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURENCES WERE REPORTED VIA
REPORTS 315/82-037,044,045,049,068,081,082,108, 316/82-054,058,062,074,076,084.
315/83-030,048,060, 316/83-022,028,034.
CODE SUBCODE S
17 REPORT 8 3 - 0 9 3 CODE TYPE NO. 0 19 3 0 11 1 0 0 0 0 0 0 0
ACTION FUTURE COMPLANT METHOD HOURS 27 SUBMITTED FORM SUB SUPPLIER MANUFACTURER LX 100 7 100 1
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
WE HAVE BEEN UNABLE TO COMPLETE THE INVESTIGATION OF THE CAUSE OF THE EVENT.
AN UPDATED REPORT WILL BE SUBMITTED AS SOON AS THE INVESTIGATION IS COMPLETED.
7 8 9 80 METHOD OF 80
FACILITY STATUS STATU
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 I 6 Z Z 33 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 11 12 13 BO
PERSONNEL INJURIES NUMBER DESCRIPTION (41) 1 N O O (40) NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 1 0 Z (42) NA
80
PUBLICITY DESCRIPTION 45 PDR ADDCK 05000316 PDR 68 69 80 6