

APPENDIX A

NOTICE OF VIOLATION

Arkansas Power and Light Company  
Arkansas Nuclear One, Units 1 and 2

Dockets: 50-313/83-19  
50-368/83-19

Licenses: DPR-51  
NPF-6

Based on the results of an NRC inspection conducted during the period of July 18-22, 1983, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987, dated March 9, 1982, the following violations were identified:

A. Failure to Meet Record Retention Requirements

Arkansas Unit 2 Technical Specification, Section 4.3.3.4, "Meteorological Instrumentation - Surveillance Requirements," requires demonstration of meteorological instrument operability at frequencies shown in Table 4.3-5 of the Technical Specifications. Procedure 1304.015, "Meteorological Instrumentation Calibration", is the implementing procedure for this surveillance. Technical Specification Section 6.10.1.d, "Administrative Controls - Record Retention," requires records of such surveillance be retained for at least 5 years.

Contrary to the above, the licensee was unable to retrieve for review by an NRC inspector the meteorological instrumentation surveillance records for the period July 16, 1981, through July 19, 1982. These documents were requested during the period July 18-22, 1983, but could not be retrieved by the licensee by September 28, 1983.

This is a Severity Level V violation (Supplement I).  
(50-368/8319-01)

B. Failure to Conduct 12 Months Emergency Preparedness Program Review

10 CFR Part 50, Section 50.54(t) states that the licensee shall provide for a review of its emergency preparedness program at least every 12 months by persons who have no direct responsibility for implementation of the emergency preparedness program and that the review shall include an evaluation for adequacy of interfaces with state and local governments and of licensee drills, exercises, capabilities, and procedures.

Contrary to this requirement, the licensee failed to provide for an independent emergency preparedness program review, including all of the required review elements, during the period November 3, 1980, through July 22, 1983.

This is a Severity Level V violation (Supplement I).  
(50-313/8319-01; 50-368/8319-02)

Pursuant to the provisions of 10 CFR 2.201, Arkansas Power and Light Company is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated: October 27, 1983