

U.S. NUCLEAR REGULATORY COMMISSION

REGION V

Report No. 50-312/91-05

License No. DPR-54

Licensee: Sacramento Municipal Utility District
P.O. Box 15830
Sacramento, California 95813

Facility Name: Rancho Seco Nuclear Generating Station

Inspection at: Clay Station, California

Inspection Conducted: April 29, 1991 through May 3, 1991, and May 17, 1991

Inspection by:

M. Cillis
M. Cillis, Senior Radiation Specialist

6/28/91
Date Signed

Approved by:

G. P. Yonas
G. P. Yonas, Chief
Reactor Radiological Protection Branch

6/28/91
Date Signed

Summary:

Areas Inspected: Routine unannounced inspection of followup items, including control of radioactive materials, surveys and monitoring, occupational radiation exposures, training and qualifications of the radiation protection, radwaste, and chemistry staff, review of the licensee's semiannual radioactive effluent report and annual radiological environmental operating report, and a tour of the licensee's facilities. Inspection procedures 92701, 83750, and 90713 were addressed.

Results: The licensee's programs examined were being maintained at their previous level of performance and were capable of achieving their safety objectives. The licensee's radiation work permit (RWP) program and program involving packaging and labeling of radioactive materials exhibited some weaknesses as described in Sections 4 and 6, respectively.

bcc w/enclosure:
Docket File
Project Inspector
Resident Inspector
G. Cook
B. Faulkenberry
J. Martin
A. Johnson
J. Zollicoffer

REGION: V/ADP
M. Illis *AK*
7/3/91

Y
GYuhas
7/3/91

Na Y
AJohnson
1/1

Na Y
RScarano
1/1

REQUEST COPY	REQUEST COPY	REQUEST COPY	REQUEST COPY
YES / NO	YES / NO	YES / NO	YES / NO

SEND TO PDR
YES / NO