

CONTROL BLOCK:

--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T		REPORT SOURCE		DOCKET NUMBER		EVENT DATE		REPORT DATE	
0	1	L	6	0	5	0	0	3	3
7	8	60	61	68	69	74	75	80	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During normal operation, Main Steam Isolation Valve "B" outboard ten (10) percent switch would not reset when tested to satisfy T.S. 3.1-1 (Note 1). The switch circuitry was then placed in the tripped condition in accordance with Technical Specifications. The event did not represent a hazard to the public health and safety. This event was previously reported in LER-82-043 Updated Report dated 01-25-83. It has been determined it should have had a separate LER as it was not in the proper time frame.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE	
I	A	E	12	E	13	I	N	S	T	R	U
9	10	11	12	13	14	15	16	17	18	19	20

LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
8	2	—	—	0	5	9	—	0	3	—	0
21	22	23	24	25	26	27	28	29	30	31	32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
X	18	F	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	A	25
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

During the 01-09-83 plant shutdown, troubleshooting commenced to investigate the reset problem. The switch was found to have mismatch between activation and striker plate in the reset direction of valve travel. Corrective action was mechanical rework of the striker plate. All MSIV 10% limit switch have been modified to prevent recurrence of the problem described in this report.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
Z	28	1	0	0	NA	B	31	Surveillance	
7	8	9	10	11	12	13	14	15	16

ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
Z	33	Z	34	NA	35	NA	
7	8	9	10	11	12	13	14

PERSONNEL EXPOSURES		DESCRIPTION	
0	0	0	NA
7	8	9	10

PERSONNEL INJURIES		DESCRIPTION	
0	0	0	NA
7	8	9	10

LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION	
Z	42		
7	8	9	10

PUBLICATION		ISSUED	
Z	44	N	44
7	8	9	10

NAME OF PREPARER: Hartford Keith

PHONE: (315) 342-3840