

DMB

NRC Form 591
(12-81)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION

1. LICENSEE City of Stillwater-Oklahoma 723 South Lewis Stillwater, Oklahoma 74074		2. REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011	
3. DOCKET NUMBER(S) 30-17209	4. LICENSE NUMBER(S) 35-19254-01	5. DATE OF INSPECTION 2-1-83	

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

1. Within the scope of this inspection, no violations were observed.

2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.

3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.

A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b), (c), (d), (e) or 34.42.

B. Containers located in _____ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).

C. **Leak tests of your** _____ sealed sources ⁶⁰⁹⁵ were not performed at the proper frequencies. ~~10 CFR~~ _____ License Condition Number **13**

D. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____

E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.

F. Reports or notifications of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____

H. **Transportation requirements of 10CFR 71.5 (a)**
A. Shipping papers were not provided as required by 49 CFR 172.200

I. _____

J. _____

K. **8302230633 830201**
NMS LIC30
35-19254-01 PDR

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

<i>Monty Harris PE City Eng</i> SIGNATURE - LICENSEE	<i>2-1-83</i> DATE	<i>CA Hooker</i> SIGNATURE - NRC INSPECTOR	<i>2/1/83</i> DATE
---	-----------------------	---	-----------------------

IE07

INSPECTOR'S REPORT
(Continuation)
Office of Inspection and Enforcement

DOCKET NO. (8 digits) OR LICENSE
NO. (BY PRODUCT) (13 digits)

03017209

REPORT

NO.

SEQ.

8301

MODULE NUMBER

5727210B

VI

VIOLATION SEVERITY OR DEVIATION

1	2	3	4	5	6
				V	

SITE RELATED

A	C
B	D

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

- 1.
- 2. 1. Contrary to license condition 13, a Troler
- 3. Model 3411B moisture density gauge
- 4. containing 8.3 millicuries of cesium-137 and
- 5. 40 millicuries of americium had not been
- 6. tested for leakage during the period October 12, 1979
- 7. to ~~June~~ February 1, 1983.
- 8.
- 9.
- 10.
- 11.
- 12.
- 13.
- 14.
- 15.
- 16.
- 17.
- 18.
- 19.
- 20.
- 21.
- 22.
- 23.
- 24.
- 25.
- 26.
- 27.
- 28.
- 29.
- 30.
- 31.
- 32.
- 33.
- 34.
- 35.
- ↓
- 36.
- 37.
- 38.
- 39.
- 40.
- 41.
- 42.
- 43.
- 44.
- 45.
- 46.

INSPECTOR'S REPORT
(Continuation)
Office of Inspection and Enforcement

DOCKET NO. (8 digits) OR LICENSE
NO. (BY PRODUCT) (13 digits)

03017209

REPORT

NO

SEQ

8301

A
B
C
D

MODULE NUMBER

5777 108

VI

VIOLATION SEVERITY OR DEVIATION

1	2	3	4	5	6
				✓	

SITE RELATED

A	C
B	D

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

2. Contrary to 10CFR 19.11 the required documents were not properly posted on February 1, 1983

INSPECTOR'S REPORT
(Continuation)
Office of Inspection and Enforcement

DOCKET NO. (8 digits) OR LICENSE
NO. (BY PRODUCT) (13 digits)

03017209

REPORT

NO

SEQ

8301

A

B

C

D

MODULE NUMBER

5816740B

V

VIOLATION SEVERITY OR DEVIATION

1 2 3 4 5 6

✓

23

SITE RELATED

A C

B D

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

3. Contrary to 10CFR 71.21 shipping papers as required by 49CFR 172.200 were not provided while transporting Type A radioactive material on public highways in the state of Oklahoma during the period February 1, 1981 to February 1, 1983