

APR 30 1991

Docket No. 030-20537

License No. 37-21345-01MD

Mallinckrodt, Inc.  
Diagnostic Imaging Services  
ATTN: Mr. Rudolph V. Gilliam  
Facility Manager and  
Radiation Safety Officer  
19 Independence Court  
Folcroft, Pennsylvania 19032

Gentlemen:

Subject: Inspection No. 030-20537/90-001

This refers to your letter dated February 15, 1991, in response to our letter dated September 18, 1990.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

With respect to measurement and control of worker's exposure to iodine-131, investigations and evaluations must be performed in accordance with 10 CFR 20.103.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Mohamed M. Shanbaky, Chief  
Nuclear Materials Safety Section A  
Division of Radiation Safety  
and Safeguards

cc:  
Public Document Room (PDR)  
Nuclear Safety Information Center (NSIC)  
Commonwealth of Pennsylvania

OFFICIAL RECORD COPY

RL MALLINCKRODT 90-01 - 0001.0.0  
04/24/91

9111180015 910430  
REG1 LIC30  
37-21345-01MD PDR

RETURN ORIGINAL TO  
REGION I

IE:07

Mallinckrodt, Inc.

2

bcc:  
Region I Docket Room (w/concurrences)

RI:DRSS  
Darden/gcb  
*J.H.D.*  
04/29/91

RI:DRSS  
*for* Shanbaky  
*J.H.Darden*  
04/29/91

OFFICIAL RECORD COPY

RI. MALLINCKRODT 90-01 - 0002.0.0  
04/24/91