

U. S. NUCLEAR REGULATORY COMMISSION

Region V

Report No. 70-1257/83-03 (IE-V-565)

Docket No. 70-1257 License No. SNM-1227 Safeguards Group III

Licensee: Exxon Nuclear Company, Inc.

777 106th Avenue Northwest

Bellevue, WA 98004

Facility Name: Exxon Nuclear Fuel Fabrication Facility

Inspection at: Horn Rapids Site, Richland, WA

Date of Last Material Control and
Accounting Inspection: February 7-11, 1983

Type of Inspection: Unannounced Material Control and Accounting

Inspectors: *L. R. Norderhaug* fr 6/15/83
G. B. Nelson, Chemist Date Signed

L. R. Norderhaug fr 6/15/83
A. V. Wieder, Safeguards Auditor Date Signed

Approved by: *L. R. Norderhaug* 6/15/83
L. R. Norderhaug, Chief Date Signed
Safeguards Branch

Inspection Summary:

Areas Inspected: Routine announced safeguards inspection in the following areas: facility organization and operations, measurement controls, shipper-receiver verification, internal control, independent safeguards inspection effort, ID and LEID verification and records and reports.

The involved 101 inspector-hours onsite by two NRC inspectors and a consultant statistician during regular hours.

Results: There were no items of noncompliance within NRC requirements in the eight areas examined.