

U. S. NUCLEAR REGULATORY COMMISSION

REGION V

Report No. 70-1257/83-04 (IE-V-575)
Docket No. 70-1257 License No. SNM-1227 Safeguards Group III
Licensee: Exxon Nuclear Company, Inc.
777 106th Avenue Northwest
Bellevue, Washington 98004
Facility Name: Exxon Nuclear Fuel Fabrication Facility
Inspection at: Horn Rapids Site, Richland, Washington
Inspection Conducted: June 23, 1983
Date of Last Physical Security Inspection Visit: December 8-12, 1980
Type of Inspection: Routine Unannounced Physical Security

Inspectors:

Clair A. Schwan
C. A. Schwan, Physical Security Inspector

07/01/83
Date Signed

L. R. Norderhaug
L. R. Norderhaug, Chief
Safeguards and Emergency Preparedness Branch

7/1/83
Date Signed

Approved by:

L. R. Norderhaug
L. R. Norderhaug, Chief
Safeguards and Emergency Preparedness Branch

7/1/83
Date Signed

Inspection Summary:

Areas Inspected: General requirements for SNM of Low Strategic Significance; and Independent Effort.

The inspection involved 11 inspector hours by two NRC inspectors. The inspection began during regular hours. One inspector hour was conducted during nonregular hours.

Results: The licensee was found to be in compliance with NRC requirements within the areas inspected.