

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 W I A I W N I P I 2 0 0 0 1 - 0 0 0 0 0 0 0 0 - 1 0 1 0 3 4 1 1 0 0 0 0 4 1 5
 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 35

CON'T
 01 REPORT SOURCE L 8 0 1 5 1 0 1 0 1 3 9 1 7 7 1 1 2 1 2 1 2 8 1 3 8 0 1 1 1 2 1 0 1 8 1 4 9
 7 8 DOCKET NUMBER 65 69 EVENT DATE 74 75 REPORT DATE 82

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 A fire rated door (#D-104) was violated causing a loss of fire boundary
 03 integrity per Tech. Spec. 3/4.7.7. The consequences of this violation
 04 are minimal since the door was capable of being closed.
 05
 06
 07
 08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 9 A B 11 11 A 12 12 E 13 13 X X X X X X X 14 14 Z 15 15 Z 16 16
 17 LER/RO REPORT NUMBER 21 22 23 24 25 26 27 28 29 30 31 32
 18 8 3 0 1 0 1 6 1 3 I L
 19 ACTION TAKEN 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
 20 A Z Z Z 0 1 0 1 0 1 N N A Z 9 9 9 9
 21 FUTURE ACTION 22 EFFECT ON PLANT 23 SHUTDOWN METHOD 24 HOURS 25 ATTACHMENT SUBMITTED 26 NRC-4 FORM SUB. 27 PRIME COMP. SUPPLIER 28 COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A fire rated door closed, pinching a welding lead and melting hole in door.
 11 Door is to be replaced. Upgrades and Modifications Manager has been
 12 directed to assure craftsmen conform to owners Industrial Safety and Fire
 13 Protection Manual, Section 7.1.4d. In the interim, the requirements of
 14 action statement 3.7.7.a were implemented.

15 FACILITY STATUS 9 B 28 10 % POWER 11 0 1 0 0 29 12 OTHER STATUS 30 N/A 13 METHOD OF DISCOVERY 44 A 31 45 DISCOVERY DESCRIPTION 46 Walkdown of fire doors
 16 ACTIVITY CONTENT 9 Z 32 10 Z 34 11 AMOUNT OF ACTIVITY 35 N/A 12 LOCATION OF RELEASE 36 N/A
 17 PERSONNEL EXPOSURES 9 0 1 0 0 37 Z 38 39 N/A
 18 PERSONNEL INJURIES 9 0 1 0 0 40 41 N/A
 19 LOSS OF OR DAMAGE TO FACILITY 9 Z 42 43 N/A
 20 PUBLICITY 9 Z 44 45 N/A
 21 NRC USE ONLY

NAME OF PREPARER R. D. Catlow PHONE: (509)377-2501 Ext. 4755