

PRINCIPAL STAFF DRMA James W. Cook Vice President Projects, Engineering and Construction.

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

July 12, 1983

50 329 50.330

Mr J G Keppler, Regional Administrator US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND EMERGY CENTER

DOCKET NO 50-329 AMD 50-330 - AMENDED MIDLAND PROJECT RESPONSE TO NRC, REGION III LETTER DATED MAY 23, 1983

File: 0485.16 UFI: 42*05*22*04 Serial: CSC-6781

0.4.2 70*01

REFERENCES: (1) 3 W Cook letter to J G Keppler, dated June 24, 1983,

Serial CSC-6764

(2) J C Keppler letter to J W Cook, dated May 23, 1983

This letter, including Attachment 1, and in addition to Reference 1, provides our amended response to Reference 2.

We appreciate your consideration in extending the due date for this response in order that our personnel could properly examine the vendor information available and hopefully provide a thorough and accurate response. This was discussed with your Mr. R. Cook. James W. Cook

JWC/BHP/klm

cc: RFWarnick, NRC Region III JJHarr'son, NRC Region III RNGardner, NRC Region III RJCook, NRC Senior Resident Inspector, Midland Site RBLandsman, NRC Region III BLBurgess, NRC Resident Inspector, Midland Site

8307250123 830712 PDR ADDCK 05000329

JUL 20 1983

TEOIN

CONSUMERS POWER COMPANY Midland Units 1 and 2 Docket No 50-329/50-330

Letter Serial CSC-6781 Dated July 12, 1983

At the request of the Commission and pursuant to the Atomic Energy Act of 1954, and the Energy Reorganization Act of 1974, as amended and the Commission's Rules and Regulations thereunder, Consumers Power Company submits the amended response to J G Keppler letter to J W Cook dated May 23, 1983.

CONSUMERS POWER COMPANY

Cook, Vice President

Projects, Engineering and Construction

Sworn and subscribed before me this 14 day of July 198.

My Commission Expires 2-4-86

PATRICIA A. PUFFER Notary Public, Bay County, MI My Commission Expires Mar. 4. 1986

Attachment 1

Amended Response to J G Keppler letter to J W Cook dated May 23, 1983

The amended response to J G Keppler letter to J W Cook dated May 23, 1983 is submitted in the following format:

NOV Item B Identification Number

- A. Statement of Original Violation (from J G Keppler letter to J D Selby dated February 8, 1983: Notice of Violation EA 83-3.)
- B. Request For Additional Information (from J G Keppler letter to J W Cook dated May 23, 1983.)
- C. Statement of Additional Information
 - 1. Admission or denial of the alleged violation
 - 2. The reasons for the violation, if admitted
 - 3. The corrective steps which have been taken and the results achieved
 - 4. The corrective steps which will be taken to avoid futher violations
 - 5. The date when full compliance will be achieved

OL/OM SERVICE LIST

Mr Charles Bechhoefer, Esq Administrative Judge Atomic Safety & Licensing Board Panel U S Nuclear Regulatory Commission Washington, DC 20555

Dr Frederick P Cowan Administrative Judge 6152 N Verde Trail Apt B-125 Boca Raton, FL 33433

Mr Michael Miller Esq Isnam, Lincoln & Beale 3 First National Plaza Suite 5200 Chicago, IL 60602

Mr D F Judd, Sr Project Manager The Babcock & Wilcox Company P O Box 1260 Lynchburg, VA 24505

Atomic Safety & Licensing Board Panel U S Nuclear Regulatory Commission Washington, DC 20555

Atomic Safety & Licensing Board Panel U S Nuclear Regulatory Commission Washington, DC 20555

Mr William D Paton, Esq Counsel for NRC Staff U S Nuclear Regulatory Commission Washington, DC 20555

Ms Barbara Stamiris 5795 North River Road Route 3 Freeland, MI 48623

Dr Jerry Harbour U S Nuclear Regulatory Commission Atomic Safety & Licensing Board Panel Washington, DC 20555 Mr Frank J Kelley, Esq
Attorney General of the
State of Michigan
Mr Stewart H Freeman, Esq
Assistant Attorney General
Environmental Protection Div
720 Law Building
Lansing, MI 48913

Mr Myron M Cherry, Esq Cherry & Flynn 3 First National Plaza Suite 3700 Chicago, IL 60602

Mr Wendell H Marshall RFD 10 Midland, MI 48640

Mr John DeMeester Dow Chemical Building Michigan Division Midland, MI 48640

Ms Mary Sinclair 5711 Summerset Street Midland, MI 48640

Mr Steve Gadler 2120 Carter Avenue St Paul, MN 55108

Mr Lee L Bishop Harmon & Weiss 1725 I Street, NW #506 Washington, DC 20006

Mr C R Stephens Docketing and Service Station Office of the Secretary U S Nuclear Regulatory Washington, DC 20555

Lynne Bernabei Governmental Accountability Project (GAP) 1901 Q Street NW Washington, DC 20009

NOV Item B - 2.a (82-22-08)

A. Statement of Original Violation

"Measures were not established for the selection and review for suitability of application of "Q" materials associated with the diesel generator exhaust muffler in that design drawings and specifications did not indicate the material identity of the installed muffler saddle supports and plates."

B. Request For Additional Information

"Regarding Item B.2.a, we reiterate our position that the lack of design documentation which specified the material requirements for the diesel generator exhaust mufflers constituted an item of noncompliance. Please provide any additional information supplied by the vendor regarding the traceability of the exhaust muffler materials, and as appropriate, your corrective actions and the results achieved, corrective actions taken to avoid further noncompliance, and the date when full compliance will be achieved."

C. Statement of Additional Information

- 1. The violation is admitted.
- 2. The violation occurred because the design intent was not implemented in the design, fabrication and inspection of the exhaust silencers by the diesel generator prime supplier, Transamerica Delavel, Inc., (TDI). This was not recognized or corrected by the design organization responsible for the procurement. The design intent was that the diesel generator exhaust silencers be subject to the appropriate elements of 10CFR50, Appendix B, and ANSI N45.2-1971.

The Bechtel procurement documents for the diesel generators specify the functional performance requirements of the diesel generators. It is not the intent to specify all details of design and construction. The expertise for the detailed design and construction of the diesel generator and accessories rests with TDI.

The procurement documents (Specification 7220-M-18, Paragraph 12.2) specified; "Quality assurance requirements are applicable to all components and assemblies which affect the reliability and ability of the equipment furnished by the Seller to perform its design function." Additionally, the specification provides a check of this requirement by requiring the vendor to submit a list of all items which he intends to supply as "Q" for review by Bechtel. When properly implemented, these requirements in Specification 7220-M-18 provide adequate direction to the vendor and control by Bechtel. Bechtel did not take action to correct the failure of TDI to fully comply with the requirements of Specification 7220-M-18, Paragraph 12.3 to submit a "list of all items to be furnished to quality control standards."

TDI has stated that they had not previously provided safety-related exhaust silencers to others, and did not consider the silencers to perform an active safety-related function. Specification requirements were not understood by TDI to apply to the exhaust silencers. As a result, the exhaust silencers were not included as an item to be safety-related. TDI procured the exhaust silencers from a subsupplier, American Air Filter (AAF), with essentially commercial quality standards. TDI did specify to AAF that material certification, weld procedures, and weld procedure qualifications be provided. AAF did not fully comply with the purchase order requirements of TDI. TDI did provide a seismic analysis of the exhaust silencers to verify the capability to withstand a safe shutdown earthquake.

The procurement documents leave the selection of materials for construction of the exhaust silencers to TDI and AAF. The materials of construction were selected by AAF and specified in the fabrication drawing based on its experience. Common grades of steel (e.g., A-36 and A-569) are typically used.

TDI provided a certificate of conformance to the purchase requirements for the exhaust sileneers and the saddle support modification plates as required by the procurement documents. That information is on site. If the exhaust sileneers and saddle support modification plates had been identified by TDI as having a safety-related function, they would have been included under the TDI quality assurance program. That program would have required actions to be taken to assure appropriate material identification and control. Specific material traceability (i.e., certified material test reports) is not applicable because of the design and function of these items.

3. The following corrective action for the exhaust silencers has been taken: We have met with TDI and visited AAF, and subsuppliers at their facilities, and reviewed all available purchasing and quality documentation. TDI will provide a Material Certificate of Compliance to confirm that the materials used were consistent with the seismic analysis. TDI has been directed to provide a fabrication inspection procedure to verify that construction of the exhaust silencer satisfies the design and seismic analysis. This inspection will be performed on site under the direction of MPQAD. If any deficiencies are found during the inspection, the silencers will be reworked to conform to the requirements.

In accordance with the partial redisposition of NCRs 4693 and 4994, muffler saddle support end and center support plate extensions are to be replaced because the dimensions of the slots/holes do not conform to the design drawings. Replacement plates will have material certificates of compliance.

Project Engineering and TDI have reviewed the technical specifications to determine if other items have been considered to be non-safety related contrary to the design intent. To date, the intake air

filters, intake air silencers, intake air flexible connectors, and exhaust expansion joints have been identified as not being considered safety related by TDI, and consequently not provided as safety related. An action plan to upgrade these items to safety-related-status by verifying that the construction of these items satisfies the design and seismic analysis is underway. NCRs M-01-9-3-158 and 4955 have been written to document the indeterminant status of these components.

Further investigation to ascertain if there are any additional suspect items in the package provided by TDI is in progress and is expected to be complete by August 15, 1983.

4. The general approach to ensure that purchased material/equipment is fabricated in accordance with the specification requirements is as follows: The Project Engineering review and acceptance of vendor submitted documents required by the specification such as drawings, procedures, and quality assurance manual; the Procurement Supplier Quality Department's performance of audits on adequacy of vendor quality program implementation and source surveillance inspections at the vendor's facility as required by the purchase order; the QC performance of receipt inspection to verify supplier submittal of the required documentation on "Q" Items that are received on site; the Supplier quality Review of the required documentation for adequacy; and MPQAD QA performance of a quality overview inspection on selected items on site.

In view of the experiences on this procurement, we will conduct a review of functional/performance oriented procurements which contain "Q" and non-"Q" items to verify that safety-related items were designated by the vendors in accordance with project design requirements. A review program and schedule will be developed by September 10, 1983.

- 5. Full compliance will be achieved when:
 - a) Receipt of the exhaust silencer Material Certificate of Compliance and completion of the fabrication inspection is expected by October 15, 1983. A schedule for any subsequent rework as a result of the inspection will be established at that time.
 - b) The exhaust silencer saddle support and center support plate extensions are replaced and NCRs 4693 and 4994 are dispositioned.
 - c) NCRs M-01-9-3-158 and 4955 will be resolved by October 15, 1983. A schedule for any subsequent rework resulting from this resolution will be established then.
 - d) Further investigation to ascertain if there are any additional suspect items in the package provided by TDI is expected to be complete by August 15, 1983.

e) The review program and schedule described in part 4 and the subsequent review is completed and any findings are addressed.

BCC W R Bird, P14-418A

* 2 * * *

J E Brunner, M1079

F W Buckman, P14-113A

D M Budzik, P124-517

M L Curland, MPQAD

M A Dietrich, Bechtel

F D Field, Union Electric

J F Firlit, JSC236A

W J Friedrich, MPQAD/QC

W D Greenwell, Bechtel AA

G A Hierzer, Bechtel

R C Hollar, Bechtel AA

E M Hughes, Bechtel AA

K E Marbaugh, QA-NO, Midland

B W Marguglio, JSC220A

D B Miller, Site Manager (3)

NRC Correspondence File, P24-517

J A Rutgers, Bechtel AA

P Steptoe, IL & B, Chicago

R A Wells, MPQAD

F C Williams, IL & B, Washington