



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

January 31, 1984

Director
Office of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555


PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

Generic Implications of Salem ATWS Events (Generic Letter 83-28)
Action 4.1 Reactor Trip System Reliability (Vendor Related Modifications)
Action 4.5 Reactor Trip System Reliability (System Functional Testing)

This letter furnishes the information committed in our November 4, 1983 submittal.

Inspections have now been completed to ensure that all vendor recommended modifications have been effected. The inspection revealed one improper Undervoltage Trip Attachment which was replaced.

Modified procedures have been developed and issued for testing the reactor trip switch gear (test of each manual trip function). The procedures were verified during the recent refueling outage for Unit 1.


David Musolf

Manager - Nuclear Support Services

DMM/ECW/bd

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
G Charnoff

8402070011 840131
PDR ADDCK 05000282
P PDR

A055
1/0