NRC FORM 366 (12-81),	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLO	CK: PLEASE PRINT OR TYPE ALL REQUIRED INFOR	
O 1 M D C O	C N Z 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 4	87 CAT 50 (5)
CON'T 0 1 REPORT SOURCE	6 0 5 0 0 0 3 1 8 0 1 2 2 7 8 3 8 0 1 2 6	1 8 4 9
	PTION AND PROBABLE CONSEQUENCES 10	
0 2 During	the past 30 days, 2 CEAs have dropped into the core. On 12-27	at
0 3 1903 CE	A-1 dropped into the core, and again on 12-28 at 0633, CEA-64	
0 4 dropped	into the core during performance of surveillance tests. Reac	tor
0 5 power w	as reduced to 70% per Technical Specification 3.1.3.1 and CEA	is
0 6 were re	aligned with their group. All other CEAs remained operable	المصمد
0 7 through	out the events.	
0 8 Similar	events: 50-317/82-36; 50-318/82-26.	
09	R B 11 X 12 X 13 X X X X X X X X X X 16 Z 16)
	10 11 12 13 18 19 20	REVISION NO.
ACTION FUTURE TAKEN ACTION	19 B 20 Z 21 D O O O N 23 N 24 N 25	COMPONENT (26) MANUFACTURER 26 Z 9 9 9 9 47
	PTION AND CORRECTIVE ACTIONS (27) cal testing of the CEAs during operation disclosed no cause f	for
1 1 this ev	ent. The licensee is continuing efforts to determine the caus	se
12 of this	event. Current traces will be taken and evaluated on each CF	EA
13 in the	regulating groups during the next scheduled test.	
1 4		90
PACILITY STATUS	POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 9 8 29 N/A C 31 Surveillance Test	32
7 8 9 10 ACTIVITY CONTE	ASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)	90
1 6 Z (33) Z 7 8 9 10 PERSONNEL	34 N/A N/A	80
1 7 0 0 0 0	TYPE DESCRIPTION (39) Z 38 N/A	
7 8 9 11 PERSONNEL NUMBER	DESCRIPTION (41)	80
7 8 9 11	40 N/A	80
LOSS OF OR DAMA	N/A	1
	8402070387 840126	SUSE ONLY
		4969/4933

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT CALVERT CLIFFS NUCLEAR POWER PLANT LUSBY, MARYLAND 20657

January 26, 1984

Dr. Thomas E. Murley Regional Administrator U. S. Nuclear Regulatory Commission Region 1 631 Park Avenue King of Prussia, PA 19406 Docket No. 50-318 License No. DPR 69

Dear Dr. Murley:

Attached is LER 83-76/3L, as required per Technical Specification 6.9.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

L. B. Russell

Plant Superintendent

LBR: JAC: bsb

cc: Director, Office Of Management Information

and Program Control

Messrs: A. E. Lundvall, Jr.

J. A. Tiernan

1022