

Docket No. 50-346
License No. NPF-3
Serial No. 978
August 11, 1983



RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Mr. Harold R. Denton, Director
Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Denton:

Toledo Edison's letter of July 22, 1983 (Serial No. 974) submitted one (1) original and twelve (12) copies of Revision 1 to the Davis-Besse Nuclear Power Station, Unit No. 1, Updated Safety Analysis Report (USAR).

Several discrepancies have been identified since the submittal of Revision No. 1:

1. A sentence was inadvertently omitted from Page 9.2-34.
2. Figure 10.4-7 was inadvertently omitted from the Revision 1 package.

Also, corrections were made to the lists which identify the page replacements.

Accompanying this letter, Toledo Edison is sending one (1) original and twelve (12) copies of replacement pages correcting the discrepancies noted above.

Very truly yours,

RPC:SGW:nlf
encl.
cc: DB-1 NRC Resident Inspector

B308190061 B30811
PDR ADDCK 05000346
K PDR

A053
1/13