




**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P O BOX 6008 • NEW ORLEANS, LOUISIANA 701



August 16, 1983

W3I83-0285  
Q-3-A35.07.71

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 71  
"Inadequate Review of CIWAs for Reportability"  
Third Interim Report

REFERENCE: LP&L Letter W3I83-0161 dated May 11, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a final report to the USNRC by August 15, 1983.

The screening and review for reportability of historical CIWAs identified by the original SCD has been completed. It was determined that several deficiencies identified on CIWAs were reportable, however, these deficiencies had been previously reported to the NRC and were not dependent on this review. It can therefore be concluded that although the CIWAs did not undergo a formal review process for 10 CFR 50.55(e) reportability, significant deficiencies were being identified by other means and were being reported to the NRC when discovered.

At the present time, the mechanism by which CIWAs will be reviewed for reportability on a permanent basis has not yet been finalized. A final report will therefore be submitted to the USNRC by November 18, 1983.

Very truly yours,

F. J. Drummond, Manager  
Engineering & Technical Services

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

8308300386 830816  
PDR ADOCK 05000382  
S PDR

IE-27 1/0