
50-382

1

.



W3P83-2581 3-A1.01.04 3-A14.09

July 29, 1983

Mr. John T. Collins U. S. Nuclear Regulatory Commission Region IV Office of Inspection and Enforcement 611 Ryan Plaza Drive Suite 1000

SUBJECT: Waterford SES Unit 3 Water Seepage in Concrete Basemat

Dear Mr. Collins:

Arlington, Texas 76012

This is to confirm discussions with you and members of your staff in which we informed you that Harstead Engineering Associates, Inc. is conducting an analysis of the water seepage which has been identified in the Waterford 3 SES basemat. A report of this analysis will be issued on or before September 1, 1983.


Yours very truly,

F. J. Drummond Manager Engineering & Technical Services

FJD/TFG/sm

cc: E. L. Blake, W. M. Stevenson, G. L. Constable

8308300734 830729 PDR ADDCK 05000382 PDR



24