

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | V | C | S | 1 | 0 | 0 | + | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 0 | 0 | 0 | 4 | [ ] [ ] | 5

01 | L | 0 | 5 | 0 | 0 | 0 | 3 | 9 | 5 | 0 | 8 | 2 | 8 | 8 | 3 | 0 | 9 | 0 | 8 | 8 | 3 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On August 28, 1983, with the Plant in Mode 1, Control Room Normal Ventilation Train "A" was declared inoperable. Technical Specification 3.7.6, "Control Room Normal and Emergency Air Handling Systems," requires that the system be operable in all modes. There were no adverse consequences due to this event. Ventilation Train "B" remained operable and the Licensee complied with the Action Statement of the aforementioned Technical Specification.

09 | S | G | E | B | I | N | S | T | R | U | I | Z | 8 | 3 | 0 | 9 | 6 | 0 | 3 | L | 0 | B | Z | Z | Z | 0 | 0 | 0 | 0 | N | N | A | B | 0 | 3 | 8

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | This event was due to the failure of the position indicator linkage on the supply damper. The supply damper and the associated ventilation fan are interlocked through the position indicator. The damper must indicate open before the fan can be started. The linkage was repaired and the unit declared operable August 30, 1983. The Licensee plans no additional corrective action

15 | E | 1 | 0 | 0 | N/A | B | Surveillance Test

16 | Z | Z | N/A | N/A

17 | 0 | 0 | 0 | Z | N/A

18 | 0 | 0 | 0 | N/A

19 | Z | N/A | 8309190486 830908 PDR ADOCK 05000395 S PDR

20 | N | N/A

NAME OF PREPARER

R. J. Bouknight

PHONE: (803) 345-5209

IEZZ 1/1

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

83 SEP 15 P 1:34

O. W. DIXON, JR.  
VICE PRESIDENT  
NUCLEAR OPERATIONS

September 8, 1983

Mr. James P. O'Reilly  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region II, Suite 2900  
101 Marietta Street, N.W.  
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station  
Docket No. 50/395  
Operating License No. NPF-12  
Thirty Day Written Report  
LER 83-096

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-096 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement for "Mode 1" of Technical Specification 3.7.6, "Control Room Normal and Emergency Air Handling Systems," on August 28, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

RJB:OWD/mac  
Attachment

cc: V. C. Summer  
E. H. Crews, Jr.  
T. C. Nichols, Jr., /O. W. Dixon, Jr.  
E. C. Roberts  
H. N. Cyrus  
Group/General Managers  
O. S. Bradham  
R. B. Clary  
C. A. Price  
A. R. Koon  
D. A. Lavigne  
J. F. Heilman

C. L. Ligon (NSRC)  
G. J. Braddick  
J. C. Miller  
J. L. Skolds  
J. B. Knotts, Jr.  
I&E (Washington)  
Document Management  
Branch  
INPO Records Center  
NPCF  
File (Lic./Eng.)

OFFICIAL COPY

IE 22

