

06 SEP 1983

Docket No. 030-02551

License No. 29-12417-01

Jerome E. Bodian, M.D.  
245 Engle Street  
Englewood, New Jersey 07631

Dear Dr. Bodian:

Subject: Inspection No. 030-02551/83-01

This refers to the routine safety inspection conducted by Mr. C. Stearns of this office on July 22, 1983 of activities authorized by NRC License No. 29-12417-01 and to the discussions of our findings held by Mr. Stearns with yourself at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your licenses. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Our inspector also verified the steps you have taken to correct the violations brought to your attention in the enclosure to our letter dated January 20, 1981. We have no further questions regarding the steps you took to correct item A.1. With regard to item A.2, this item has recurred.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. This violation has been categorized by severity level in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register Notice (47 FR 9987) dated March 9, 1982. You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

Item A in the Notice of Violation enclosed with this letter was identified during a previous inspection of your licensed activities on January 2, 1981, and was documented in the enclosure to our letter dated January 20, 1981. Your letter to this office dated February 19, 1981 stated that would ensure your survey meter was calibrated yearly. From our July 22, 1983 inspection, it appears that the stated corrective actions were not effective since this item has recurred. Recurrent and uncorrected violations are given additional weight in the consideration and selection of appropriate enforcement action. Therefore, in your response to this letter, you should give particular attention to those actions taken or planned to ensure that identified items of noncompliance will be completely corrected and will not recur.

OFFICIAL RECORD COPY

341KINNEMAN8/21/83 - 0001.0.0  
08/29/83

8309200002 830906  
NMS LIC30  
29-12417-01 PDR

TE07  
1/1

0 6 SEP 1983


In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us in this matter is appreciated.

Sincerely,

**Original Signed By:**

  
Thomas T. Martin, Director  
Division of Engineering and  
Technical Programs

Enclosure: Appendix A, Notice of Violation

cc:

Public Document Room (PDR)

Nuclear Safety Information Center (NSIC)

State of New Jersey

bcc:


Region I Docket Room (w/concurrences)

Senior Operations Officer (w/o encls)

 RI:DETP

Kinneman/pja

8/1/83

 RI:DETP

Stearns

9/1/83

OFFICIAL RECORD COPY

341KINNEMAN8/21/83 - 0002.0.0  
08/29/83