

SUPPLEMENTARY INFORMATION TO
LER 82-106/01 X-3

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.7.7
Reported Under Technical Specification: 6.9.1.12.b

Event Narrative:

This is an update to previous reports submitted on November 17, 1982, April 7, 1983, and July 12, 1983. The following paragraphs describe the event reported.

During a "1982" NRC audit of LCO's, it was discovered that an action statement was entered for Technical Specification 3.7.7 on July 30, 1982, and a required Special Report pursuant to Technical Specification 6.9.2 was not filed.

The LCO was entered due to the incomplete installation of fire rated barriers on some safety related cables, conduits and cable trays. An hourly fire watch was established, however, an incident report was not filed as required by plant procedures. Therefore, the Special Report required by Technical Specification 3.7.7 was not filed.

This report was submitted pursuant to Technical Specification 6.9.1.12.b since the Special Report required by the LCO was not filed within the time limit of Technical Specification 3.7.7 Action (a). The plant is currently operating under the Technical Specification 3.7.7 action statement.

During an inspection of completed work to correct the deficiencies, Field Engineering discovered similar deficiencies not previously identified by the Architect Engineer. This event was reported as LER 83-010/99 X-0.

Work has been completed to correct the deficiencies described above. The LCO will remain in effect until processing and closeout of the work packages are complete. This is a final report.



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640 JACKSON, MISSISSIPPI 39205

83 SEP 19 49:53
September 15, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Required
Incident Report and Special
Report Not Submitted Per
Plant Procedures
LER 82-106/01 X-3
AECM-83/0582

This letter submits an update to a previous update report submitted on July 12, 1983. The event for which the report was submitted occurred on November 4, 1982, when a Nuclear Regulatory Commission (NRC) audit of Limiting Conditions for Operation (LCO) revealed that an action statement was entered for Technical Specification 3.7.7 on July 30, 1982, and a required Special Report pursuant to Technical Specification 6.9.2 was not filed. The report was submitted pursuant to Technical Specification 6.9.1.12.b since the Special Report required by the LCO was not filed within the time limit of the action statement.

Work has been completed to correct the deficiencies for which the action statement was entered. The LCO will remain in effect until processing and closeout of the work packages are complete. Attached is LER 82-106/01 X-3, which is a final report.

Yours truly,

for L. F. Dale
Manager of Nuclear Services

EBS/SHH:sap
Attachment

cc: (See Next Page)

ORIGINAL COPY

IE-22

MISSISSIPPI POWER & LIGHT COMPANY

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555