## THE CINCINNATI GAS & ELECTRIC COMPANY



September 15, 1983 LOZ-83-0140

J. WILLIAMS, JR BENIOR VICE PRESIDENT NUCLEAR OPERATIONS

Docket No. 50-358

U.S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Attention: Mr. J.G. Keppler

Regional Administrator

Gentlemen:

WM. H. ZIMMER NUCLEAR POWER STATION - UNIT 1 RE: 10CFR50.55(e), ITEM S-12, BERGEN-PATTERSCN EA-3 PIPE CLAMP INCORRECTLY USED IN SUPPORT DESIGN W.O. 57300, JOB E-5590, FILE NO. 956C, S-12

This letter constitutes a supplement to our interim report, LOZ-83-0115, dated August 25, 1983. The final sentence in that report identifies it as an interim report. The first sentence in that report should be changed to read "interim report", in order to correctly reflect the intent of the submittal.

Completion of the corrective action (i.e. installation and QC acceptance of the affected supports) is contingent upon the release of the NRC November 12, 1982 "Order to Show Cause and Order Immediately Suspending Construction". A final report will be submitted upon completion of the corrective action.

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

WILLIAMS, JR SENIOR VICE PRESIDENT

DJS/sfr

SEP 1 9 1983

Mr. J.G. Keppler Regional Administrator September 15, 1983 LOZ-83-0140 Page 2

cc: NRC Office of Inspection & Enforcement
Washington, D.C. 20555
NRC Senior Resident Inspector
ATTN: T.P. Gwynn
NRC Zimmer Project Inspector, Region III
ATTN: E.R. Schweibinz