NRC FORM 366 (12-81) 10 CFR 50	LICENSEE EVENT REPORT	APPROVED BY OMB
CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL R	EQUIRED INFORMATION)
O 1 A L J M F 2 2 C	0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 LICENSE NUMBER 25 26 LICEN	1 1 1 1 57 CAT 58 5
CON T   0 1   REPORT   L 6 0 5 0	0 0 0 3 6 4 7 0 8 2 1 8 3 8 OCKET NUMBER 68 69 EVENT DATE 74	0   9   1   9   8   3   9
event description and proba At 1128 on 8/21/83, o	BLE CONSEQUENCES (10) during the performance of FNP-2-STP-11.	8 (Residual Heat Remo-
o 3 val System Check Valv	ves Inservice Test) the 2B RHR pump was	declared inoperable
o 4 when it failed to sta	art. Tech. Spec. 3.5.2, in part, requi	res this pump to be
o 5   operable. Tech. Spec	c. 3.5.2 action statement requirements	were met. Health/
o 6 safety of the public	was not affected.	
0 7		
08		80
SYSTEM CALL	DE SUBCODE COMPONENT CODE SUBCO	DE SUBCODE
0 9 S F (1) 1	( 12 Z 13 P U M P X X 14 B	(15) (16)
17 REPORT   8 3   -	0 3 5   0 3 L	
ACTION FUTURE EFFECT TAKEN ACTION ON PLANT	METHOD HOURS (22) SUBMITTED FORM SUB.	PRIME COMP. COMPONENT SUPPLIER MANUFACTURER 26
E (18) Z (19) Z (20)	Z 2) 0 0 0 0 N 23 Y 24	N (25) I 0 7 5
CAUSE DESCRIPTION AND CORRECT This event was caused	ctive actions ② d by a variable resistor in the breaker	closing spring
charging motor circuit	it being out of adjustment. The resist	or was adjusted and
1 2   following verification	on of proper breaker operation, the 2B	RHR pump was declared
operable at 1235 on 8	3/21/83.	
1 4		
FACILITY   STATUS   POWER	NA B 31 Surveillance T	est 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT O	NA   NA LOCATION O	of RELEASE (36)
PERSONNEL EXPOSURES NUMBER TYPE DESCRIP	TION (39) NA	80
7 8 9 11 12 13	IVA .	80
NUMBER DESCRIPTION (41)	NA	80
LOSS OF OR DAMAGE TO FACILITY 43	NA	
7 8 9 10 PUBLICITY		NRC USE ONLY
2 0 N 44	NA	
NAME OF PREPARED	W. G. Hairston, III PHONE	(205) 899-5156
8309260327 830919 PDR ADOCK 05000364 PDR		