




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 15, 1983

W3I83-0306
Q-3-A35.07.76



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 76
"Damage to Pressurizer Heaters During Hot
Functional Testing"
Third Interim Report

REFERENCE: LP&L letter W3I83-0234 dated July 13, 1983

Dear Mr. Collins:

The above referenced letter indicated that a Final Report would be submitted to the USNRC by September 15, 1983.

At the present time, all thirty (30) of the pressurizer heaters have been replaced. Welding and Non-Destructive Testing (NDE) associated with the corrective action was performed in accordance with Section XI of the ASME Code. Closure of this SCD is pending the review of the supporting documentation.

A Final Report will, therefore, be submitted to the USNRC on October 14, 1983.

Very truly yours,

F. J. Drummond
Nuclear Services Manager

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

8310030363 830915
PDR ADDCK 05000382
S PDR

IE-27 1/0